



The disconnect switch for the furnace was relocated during replacement and attached to the main plenum. A screw used to attach the junction box, damaged one of the wires and energized the ductwork. It is very lucky that someone was not killed as a result of this unprofessional installation.