



This main beam is located in a 3 year old home. Green lumber was used during construction and as the beam dried, it warped over 4 inches. It was underneath the tile fireplace hearth and causing the grout and tiles to crack. A 10 foot section of the beam was replaced.