



The roof sheathing on this four-plex was saturated. The moisture reading was 100% and there were mushrooms and mold growing throughout the attic area of the top two units. The roof and sheathing were needing replacement and the moisture was also starting to affect the rafters.