



The chimney mortar of this 85 year old home had softened and eroded. Almost the entire chimney had to have the mortar replaced. The hole was allowing water into the wall around the fireplace. The interior paint was starting to discolor and the plaster walls were very moist.