



A leak in the foundation wall has let moisture into the crawl space over a prolonged period of time. The moisture caused the support to rot and also allowed dampwood termites to get a foothold in this area. Considerable damage needed to be repaired.