



During initial construction, the skylight was installed in the wrong position. It was moved and the hole was patched. One of the trusses had been cut and improperly repaired. A structural engineer was contacted for the proper method of repair. This was a one year warranty inspection. The engineer fees and repairs were made by the unhappy builder. Even new construction should have a home inspection performed.