



From the side, this floor joist looked to be in good condition. While probing with a screwdriver, it was found that the termite damage was so extensive, the joist was hollow. The screwdriver went all the way through one side and out the other.