



This heating system was a hot water system. This oil burner heat chamber was cracked in numerous areas and had not been serviced in what appears to be decades. Follow-up found that the unit was beyond repair and a new unit was installed.