



All the insulation in the attic was installed incorrectly. The vapor barrier that is visible should be facing the living space. By installing in this position, condensation can build up within the insulation between the vapor barrier and the ceiling. This could lead to a high moisture area that is subject to mold growth.