



This home had a bad termite infestation at the far end of a very low crawlspace. The complete sill plate was badly damaged and would need replacement. This would entail jacking the home up for repairs. The termites had also moved up into the walls and there were extensive repairs needed.