



One of the heating ducts was reused in another area. Since it had been previously cut, the installer decided to “patch” the unit with a left over Pepsi carton. This did keep the crawlspace warm, it was the bathroom that was cold.